

GREENWORKS SERVICE COMPANY

855-349-6757

support@greenworksinspections.com https://greenworksinspections.com



STRUCTURAL ENGINEERING INSPECTION



Inspector
Steven Wilson
EIT #62191, TBPE Firm #20170, MOLD FIRM
#AC01162, LEAD FIRM #2110697, ASBESTOS AGENCY
#100576, TPCL FIRM #0761253
512-994-2323

steven.wilson@greenworksengineering.com

GreenWorks Service Company Page 1 of 28

TABLE OF CONTENTS

1: General	4
2: Observations - Exterior	12
3: Structural Review	23
4: Professional Engineer Stamp	24

GreenWorks Service Company Page 2 of 28

SUMMARY

- ⚠ 2.1.1 Observations Exterior Exterior Distress: Signi cant Corrosion to Steel Connection
- ⚠ 2.1.2 Observations Exterior Exterior Distress: Signi cant Corrosion With Section Loss
- ⚠ 2.1.3 Observations Exterior Exterior Distress: Signi cant Corrosion to Stair step Support
- A
- 2.1.4 Observations Exterior Exterior Distress: Signi cant Corrosion of steel Decking under stair landing
- ▲ 2.1.5 Observations Exterior Exterior Distress: Signi cant corrosion to corrugated Decking
 - 2.1.6 Observations Exterior Exterior Distress: Separation of Glulam members
 - 2.1.7 Observations Exterior Exterior Distress: Moderate Corrosion on steel joist
 - 2.1.8 Observations Exterior Exterior Distress: Moderate Corrosion to Steel Beam
 - 2.1.9 Observations Exterior Exterior Distress: Minor Corrosion on Steel Joist
 - 2.1.10 Observations Exterior Exterior Distress: Bulge and Cracks in Stucco
 - 2.1.11 Observations Exterior Exterior Distress: Minor Corrosion to Steel Beam
- 3.1.1 Structural Review Framing Review Conclusions: Building is at risk of collapse

GreenWorks Service Company Page 3 of 28

1: GENERAL

Information

Project Information: GreenWorks Project Information: Inspection Project Information: Report Issue

Project Number Date Date

2023-07-10 2023-07-17

Building Information: Building Building Information: Framing Building Information: Exterior

Type Type Wall Type

Three Story Multi-Family Wood-framed, Steel-framed, Lap Siding, Stucco

Residential w/ Below-Grade Concrete-framed

Building Information: Foundation

Type
Concrete Piers w/ Steel Beams

Parking Structure


General: Purpose - Framing Review

As requested, personnel of GreenWorks Engineering and Consulting have completed a structural review of the address referenced above. The purpose of the observation was to collect information necessary to assess the condition and performance of the existing structure, including the below-grade garage, balconies, and facade. No inspection of the interior spaces was performed.


Some data collected in the form of photographs of the observed distress is presented in this report. These photographs are included for reference and are intended only to represent the distress generally found throughout the structure. They do not represent a comprehensive catalog of all of the distress present in the structure.

General Property Photos


GreenWorks Service Company Page 4 of 28




GreenWorks Service Company Page 5 of 28




GreenWorks Service Company Page 6 of 28




GreenWorks Service Company Page 7 of 28



GreenWorks Service Company Page 8 of 28



GreenWorks Service Company Page 9 of 28



GreenWorks Service Company Page 10 of 28



GreenWorks Service Company Page 11 of 28

2: OBSERVATIONS - EXTERIOR

Information

Exterior Distress: Downspout Terminations

At foundation

A properly functioning gutter system will minimize ponding, soil loss and erosion, and can help control seasonal movement of the foundation. The gutter system should discharge the water a minimum of 5 feet from the foundation or into a below-grade drainage system.





Exterior Distress: Trim Separation







Exterior Distress: Patio Cracks

GreenWorks Service Company Page 12 of 28




Exterior Distress: Stucco Cracks



Exterior Distress: Siding separation

GreenWorks Service Company Page 13 of 28



GreenWorks Service Company Page 14 of 28



Exterior Distress: Rotted siding Unit 220, 224, 222, 2nd oor laundry, 102



Exterior Distress: Rotted Trim Unit 207, 209, 210

GreenWorks Service Company Page 15 of 28







Exterior Distress: Signi cant Corrosion to Stair Railing

East Stair






Structural concerns

2.1.1 Exterior Distress SIGNIFICANT CORROSION TO STEEL CONNECTION





GreenWorks Service Company Page 16 of 28



2.1.2 Exterior Distress



SIGNIFICANT CORROSION WITH SECTION LOSS

Signi cant corrosion was present with section loss to steel joists



GreenWorks Service Company Page 17 of 28



2.1.3 Exterior Distress

SIGNIFICANT CORROSION TO STAIR STEP SUPPORT
WEST STAIRS 1ST FLIGHT



5 Angles need to be replaced



2.1.4 Exterior Distress



GreenWorks Service Company Page 18 of 28

SIGNIFICANT CORROSION OF STEEL DECKING UNDER STAIR LANDING

UNIT 114





2.1.5 Exterior Distress


A Safety Hazard

SIGNIFICANT CORROSION TO CORRUGATED DECKING

PARKING GARAGE, WEST & EAST STAIRS



GreenWorks Service Company Page 19 of 28



2.1.6 Exterior Distress

SEPARATION OF GLULAM MEMBERS

UNIT 113



2.1.7 Exterior Distress

MODERATE CORROSION ON STEEL JOIST
CENTRAL AND NORTH CONCRETE WALLS






GreenWorks Service Company Page 20 of 28

2.1.8 Exterior Distress

MODERATE CORROSION TO STEEL BEAM

EAST STAIRS, PARKING 205



2.1.9 Exterior Distress

MINOR CORROSION ON STEEL JOIST

NORTHEAST CORNER



2.1.10 Exterior Distress

BULGE AND CRACKS IN STUCCO UNIT 202

Bulging Stucco is typically an indication of water intrusion in the wall.



GreenWorks Service Company Page 21 of 28

2.1.11 Exterior Distress

MINOR CORROSION TO STEEL BEAM

PARKING 106



GreenWorks Service Company Page 22 of 28

3: STRUCTURAL REVIEW

Information

Framing Review Conclusions: Structural Review - Inadequate

Based on our observations, there is signi cant structural damage due to extensive water intrusion, primarily at the balconies and the plaza above garage and the existing structure and is inadequate to support the current loads. It is our opinion that the structure will require extensive repairs to the concrete, steel, and wood framing to bring the structure to adequacy. We recommend performing the required repairs only according to structural repair plans that have been stamped and signed by a licensed professional engineer. If requested GreenWorks Engineering can provide the required structural plans.

Structural concerns

3.1.1 Framing Review Conclusions



BUILDING IS AT RISK OF COLLAPSE

During the site visit, at least 7 steel oor trusses were observed to be completely corroded through with signi cant section loss, and several steel beam connections were compromised. Although it is impossible to predict when structural failure will occur, steel corrosion tends to accelerate quickly, and it is our opinion that temporary shoring should be placed in the locations marked as Safety Hazards throughout this report. If desired, a GreenWorks representative can meet on-site to indicate locations where temporary shoring should be placed.

4: PROFESSIONAL ENGINEER STAMP

Information

Report Prepared By: Prepared by Zain

Maredia, E.I.T.

Professional Engineer Stamp: Reviewed by Stephanie Solo, P.E. GreenWorks Service Company



Vice President of Engineering

Texas Registered Engineering Firm 20170

Reviews enable us to continue providing the best experience possible for you and they also help homeowners like you to make con dent decisions about their engineering needs. Click here to leave a review.

GreenWorks Service Company Page 23 of 28


Limitations

GENERAL


The opinions and recommendations contained in this report are based on the visual observation of the then current conditions of the structure and the knowledge and experience of the engineer. The evaluation was limited to visual observations and areas not visible, accessible, or hidden behind furniture and appliances were not included in the evaluation. The evaluation did not include any soil sampling or testing.

The evaluation did not include any assessment of the existing foundation, plumbing, or soil and no implication is made on the compliance or non-compliance of the house with old or current building codes. No veri cation was made of the existing concrete strength, thickness, reinforcement nor capacity to support any load.


No guarantee or warranty as to the future performance or need for repair of the structure is intended or implied. Limits of liability for any claims with respect to this report is limited to the fees paid for services and anyone relying on the content of this report agrees to indemnify GreenWorks Service Company for all costs exceeding this fee.




GreenWorks Service Company Page 24 of 28




GreenWorks Service Company Page 25 of 28



GreenWorks Service Company Page 26 of 28



GreenWorks Service Company Page 27 of 28



GreenWorks Service Company Page 28 of 28