



Radon Inspection Report

Document Generated
05/26/2023

Document Number
RP22304130018_19May23_1019

Measurement Information

Client Name

GreenWorks Client

Measurement Started

05/19/2023 10:19

Measurement Ended

05/21/2023 09:19

Inspection Duration

48 hour (Data No : 47)

Measurement Location

123 GreenWorks Way
San Antonio, Texas 78247



Measurement Details

Building Type

House

Room Type

Living room

Floor

1st floor

Building year

1989

Device Information

Device S/N

RP22304130018

Device calibrated

04/13/2023

Tester Information

Tester Name

Aaron Cantu

Tester Email

aaron.cantu@greenworksinspections.com

Tester Address

-

Certification # (State-License #)

Tester Phone

Inspection Information

Delay Time

0 hour

Inspection Duration

47 hours

Measurement Started

FRI , 05/19/2023 10:19 AM

Measurement Ended

SUN , 05/21/2023 09:19 AM

Measurement Radon Concentration Max

0.8 pCi/L

Measurement Radon Concentration Min

0.0 pCi/L

Overall Average Radon Concentration

0.4 pCi/L

Historical Radon Trend




Table of Hourly Radon Measurements

Radon Concentration Average: 0.4 pCi/ℓ

Timestamp	Radon Value	Temp(F)	RH(%)	Timestamp	Radon Value	Temp(F)	RH(%)
05/19/23 11:19	0.2	73	65	05/20/23 11:19	0.2	73	61
05/19/23 12:19	0.6	73	63	05/20/23 12:19	0.4	72	61
05/19/23 13:19	0.1	73	63	05/20/23 13:19	0.4	70	54
05/19/23 14:19	0.0	73	62	05/20/23 14:19	0.2	68	52
05/19/23 15:19	0.2	73	62	05/20/23 15:19	0.2	68	51
05/19/23 16:19	0.4	74	61	05/20/23 16:19	0.4	68	50
05/19/23 17:19	0.5	73	60	05/20/23 17:19	0.5	68	51
05/19/23 18:19	0.2	73	58	05/20/23 18:19	0.4	68	51
05/19/23 19:19	0.4	73	58	05/20/23 19:19	0.4	68	52
05/19/23 20:19	0.4	73	60	05/20/23 20:19	0.4	68	51
05/19/23 21:19	0.4	73	62	05/20/23 21:19	0.3	68	52
05/19/23 22:19	0.3	73	63	05/20/23 22:19	0.4	68	54
05/19/23 23:19	0.3	73	64	05/20/23 23:19	0.4	68	54
05/20/23 00:19	0.5	73	65	05/21/23 00:19	0.7	69	55
05/20/23 01:19	0.2	73	66	05/21/23 01:19	0.6	68	54
05/20/23 02:19	0.4	73	65	05/21/23 02:19	0.5	68	56
05/20/23 03:19	0.5	73	63	05/21/23 03:19	0.6	68	56
05/20/23 04:19	0.4	73	62	05/21/23 04:19	0.7	68	56
05/20/23 05:19	0.5	73	62	05/21/23 05:19	0.4	68	56
05/20/23 06:19	0.2	73	62	05/21/23 06:19	0.4	69	58
05/20/23 07:19	0.5	73	62	05/21/23 07:19	0.8	68	58
05/20/23 08:19	0.4	73	62	05/21/23 08:19	0.4	69	60
05/20/23 09:19	0.5	73	62	05/21/23 09:19	0.5	68	60
05/20/23 10:19	0.4	73	61				

* Temperature and humidity can vary depending on environmental conditions.
* The test data was taken from a testing device approved by the National Radon Proficiency Program.

Radon Concentration Average: 0.4 pCi/l

Timestamp	Radon Value	Temp(F)	RH(%)	Timestamp	Radon Value	Temp(F)	RH(%)
Event							
Movement	05/21/23 18:51						
Movement	05/21/23 18:54						
Movement	05/21/23 18:55						

* Temperature and humidity can vary depending on environmental conditions.

* The test data was taken from a testing device approved by the National Radon Proficiency Program.